

SECURITIES AND EXCHANGE COMMISSION

SEC FORM 17-C

**CURRENT REPORT UNDER SECTION 17
OF THE SECURITIES AND REGULATION CODE
AND SRC RULE 17.2 (c) THEREUNDER**

- | | |
|---|--|
| 1. Date of Report: | 2 July 2026 |
| 2. SEC Identification Number: | 39274 |
| 3. BIR Tax Identification Number: | 000-506-020-000 |
| 4. Exact Name of Issuer as specified in its charter | ACEN CORPORATION |
| 5. Province, country or other jurisdiction of incorporation | Makati City, Philippines |
| 6. Industry Classification Code | (SEC Use Only) |
| 7. Address of principal office | 35th Floor, Ayala Triangle Gardens Tower 2, Paseo de Roxas corner Makati Avenue, Makati City |
| Postal Code | 1226 |
| 8. Issuer's telephone number, including area code | (632) 7730 6300 |
| 9. Former name or former address, if changed since last report | Not Applicable |
| 10. Securities registered pursuant to Sections 8 and 12 of the SRC or Sections 4 and 8 of the RSA | |

Title of Each Class	Number of Shares of Common Stock Outstanding and Amount of Debt Outstanding
Common Shares	39,951,435,064
Series A Preferred Shares	8,341,500
Series B Preferred Shares	16,658,500

- | | |
|---|---------------------------------------|
| 11. Indicate the item numbers reported herein | Other Matters. Please see attachment. |
|---|---------------------------------------|

SIGNATURE

Pursuant to the requirements of the Securities and Regulation Code, the issuer has duly caused this report to be signed on its behalf by the undersigned hereunto duly authorized.

Makati City, 2 July 2026.

ACEN CORPORATION
Issuer/Registrant
DocuSigned by:

ALAN T. ASCALON
Assistant Corporate Secretary

Other Matters:

Alaminos BESS Inc. (ABI), a subsidiary of ACEN CORPORATION, received a notice on 1 July 2026 from the Philippine Electricity Market Corporation (PEMC) imposing a ₱78,713.16 financial penalty for non-compliance with the Reserve Conformance Standards (RCS) for the April 2026 billing period. The penalty was imposed under the Ancillary Services Monitoring Manual, which sets the standards and parameters for assessing Ancillary Service Providers' (ASPs) compliance with their reserve obligations.

Based on PEMC's assessment, the non-compliance involved fifty-one (51) intervals beginning March 26, 2026, during which ABI did not meet certain RCS requirements for its Regulating Reserve and Contingency Reserve services. The resulting penalty amounted to ₱78,713.16. The non-compliance was attributable to operational limitations encountered during the relevant intervals.

ABI will settle the amount in accordance with PEMC's billing and settlement procedures.

ABI remains committed to complying with applicable market rules and supporting the reliable operation of the grid.